

07173 - Pro Booster 3100 (12v) Exploded Diagram & Parts List



Ref. No.	Description	SIP Part No.	Ref. No.	Description	SIP Part No.
000044	Front case	PW02-00213	001091	Battery cable 2.5mm red	PW02-00223
000045	Rear case	PW02-00214	001121	Cable 2.5mm black	PW02-00224
000190	Cable holder	PW02-00215	001122	Battery cable 2.5mm black	PW02-00225
000204	Clamp holder	PW02-00216	001333	Clamp cable 25mm	PW02-00226
000672	Negative clamp	PW02-00234	002012	Label	PW02-00227
000673	Positive clamp	PW02-00235	002184	Charger fuse 5A	PW02-00228
000815	Battery	18895	002185	Charger end	PW02-00229
000838	12v socket	PW02-00219	002187	12v lead	PW02-00230
000839	Circuit breaker	PW02-00220	002194	Charger	17291
000854	Control circuit	PW02-00221	002259	Front cover label	PW02-00259
000870	Test switch	PW02-00222	002260	Handle label	PW02-00233